Product Preview Low Voltage CMOS 1:18 Clock Distribution Chip

The MPC909 is a 1:18 low voltage clock distribution chip. The 18 outputs are LVCMOS or LVTTL compatible and feature the drive strength to drive 50Ω series or parallel terminated transmission lines. With output-to-output skews of 250ps, the MPC909 is ideal as a clock distribution chip for the cost sensitive, high performance designs. With low cost as one of the critical parameters, technology, design and test choices were made which adversely affect part-to-part skew performance. For very high performance applications, where part-to-part skew is critical, please refer to the MPC940 datasheet.

- LVCMOS/LVTTL Clock Inputs and Outputs
- 250ps Maximum Targeted Output-to-Output Skew
- Drives Up to 36 Independent Clock Lines
- Maximum Output Frequency of 100MHz
- High Impedance Output Enable
- 32-Lead TQFP Packaging
- 3.3V VCC Supply Voltage

With a low output impedance, in both the HIGH and LOW logic states, the output buffers of the MPC909 are ideal for driving series terminated transmission lines. More specifically, each of the 18 MPC909 outputs can drive two series terminated 50 Ω transmission lines. With this capability, the MPC909 has an effective fanout of 1:36 in applications where each line drives a single load. With this level of fanout, the MPC909 provides enough copies of low skew clocks for many high performance synchronous systems.

The MPC909 is fully 3.3V compatible. The 32-lead TQFP package was chosen to optimize performance, board space and cost of the device. The 32-lead TQFP has a 7x7mm body size with a conservative 0.8mm pin spacing.

 LOW VOLTAGE CMOS

 1:18 CLOCK

 DISTRIBUTION CHIP

 INFRIBUTION CHIP

MPC909

This document contains information on a product under development. Motorola reserves the right to change or discontinue this product without notice.



6/97







Figure 2. 32-Lead Pinout (Top View)

FUNCTION TABLE

OE	Output			
0	High–Z			
1	Enabled			

ABSOLUTE MAXIMUM RATINGS*

Symbol	Parameter	Min	Мах	Unit
VCC	Supply Voltage	-0.3	3.6	V
VI	Input Voltage	-0.3	V _{DD} + 0.3	V
IIN	Input Current		±20	mA
T _{Stor}	Storage Temperature Range	-40	125	°C

* Absolute maximum continuous ratings are those values beyond which damage to the device may occur. Exposure to these conditions or conditions beyond those indicated may adversely affect device reliability. Functional operation under absolute–maximum–rated conditions is not implied.

DC CHARACTERISTICS (TA = 0° to 70°C, V_{CC} = 3.3V $\pm 5\%$, or 2.5V $\pm 5\%$)

Symbol	Characteristic	Min	Тур	Max	Unit	Condition
VIH	Input HIGH Voltage	2.0		3.6	V	
VIL	Input LOW Voltage			0.8	V	
VOH	Output HIGH Voltage	2.4			V	Note 1., I _{OH} = -20MA
V _{OL}	Output LOW Voltage			0.5	V	Note 1., I _{OL} = 20MA
I _{IN}	Input Current			TBD	μΑ	
C _{IN}	Input Capacitance			TBD	pF	
C _{pd}	Power Dissipation Capacitance			TBD	pF	
ICC	Maximum Quiescent Supply Current			TBD	mA	

1. The MPC909 outputs can drive series or parallel terminated 50Ω (or 50Ω to V_{CC}/2) transmission lines on the incident edge.

AC CHARACTERISTICS (TA = 0° to 70°C, V_{CC} = 3.3V $\pm 5\%$, or 2.5V $\pm 5\%$)

Symbol	Characteristic	Min	Тур	Max	Unit	Condition
F _{max}	Maximum Input Frequency			100	MHz	Note 2.
^t pd	Propagation Delay LVCMOS_CLK to Q OE to Q	1.0 1.0		5.0 8.0	ns	Note 2.
^t sk(o)	Output-to-Output Skew			250	ps	Note 2.
^t pwo	Output Pulse Width	45		55	%	Note 2., Measured at $V_{CC}/2$
t _r , t _f	Output Rise/Fall Time	0.20		1.0	ns	0.8V to 2.0V

2. Driving 50Ω transmission lines

OUTLINE DIMENSIONS



MPC909

Motorola reserves the right to make changes without further notice to any products herein. Motorola makes no warranty, representation or guarantee regarding the suitability of its products for any particular purpose, nor does Motorola assume any liability arising out of the application or use of any product or circuit, and specifically disclaims any and all liability, including without limitation consequential or incidental damages. "Typical" parameters which may be provided in Motorola data sheets and/or specifications can and do vary in different applications and actual performance may vary over time. All operating parameters, including "Typicals" must be validated for each customer application by customer's technical experts. Motorola does not convey any license under its patent rights nor the rights of others. Motorola products are not designed, intended, or authorized for use as components in systems intended for surgical implant into the body, or other applications intended to support or sustain life, or for any other application in which the failure of the Motorola product could create a situation where personal injury or death may occur. Should Buyer purchase or use Motorola products for any such unintended or unauthorized application, Buyer shall indemnify and hold Motorola and its officers, employees, subsidiaries, affiliates, and distributors harmless against all claims, costs, damages, and expenses, and reasonable attorney fees arising out of, directly or indirectly, any claim of personal injury or death associated with such unintended or unauthorized use, even if such claim alleges that Motorola was negligent regarding the design or manufacture of the part. Motorola and was negligent regarding the design or manufacture of the part. Motorola and was negligent regarding the design or manufacture of the part. Motorola and was negligent regarding the design or manufacture of the part. Motorola and was negligent regarding the design or manufacture of the part. Motorola and was negligenter trademarks of

How to reach us:

USA/EUROPE/Locations Not Listed: Motorola Literature Distribution; P.O. Box 5405, Denver, Colorado 80217. 303–675–2140 or 1–800–441–2447 Mfax is a trademark of Motorola, Inc.

JAPAN: Nippon Motorola Ltd.: SPD, Strategic Planning Office, 4–32–1, Nishi–Gotanda, Shinagawa–ku, Tokyo 141, Japan. 81–3–5487–8488

Mfax[™]: RMFAX0@email.sps.mot.com – TOUCHTONE 602–244–6609 – US & Canada ONLY 1–800–774–

INTERNET: http://motorola.com/sps



TOUCHTONE 602–244–6609
 ASIA/PACIFIC: Motorola Semiconductors H.K. Ltd.; 8B Tai Ping Industrial Park,
 US & Canada ONLY 1–800–774–1848
 51 Ting Kok Road, Tai Po, N.T., Hong Kong. 852–26629298